



LuK Service Info



Part Nr: 133 0608 10 — 330mm DBFP

Part Nr: 133 0271 10 — 330mm TBFR


Manufacturer: NEW HOLLAND FORD


Model: 3000, 4000, 5000, Series & Industrial


Art.-Nr.: **133 0608 10 / 133 0271 10**


Info: 133 0608 10 replaces/ersetzt/remplace/
sustituye a/sostituisce 130 0018 10


133 0271 10 replaces/ersetzt/remplace/
sustituye a/sostituisce 133 0017 10

 When replacing a 4 lever coil spring clutch with LuK diaphragm type clutch, shims are not required.

 Wenn die 4-Hebel-Schraubenfederkupplung durch eine LuK-Tellerfederkupplung ersetzt wird, entfalten die Segmentbleche.

 Le remplacement d'un embrayage à ressorts hélicoïdaux à 4 leviers par un embrayage à diaphragme LuK ne requiert pas de cales de réglage.

 Al reemplazar el embrague de muelles helicoidales con 4 patillas por el de diafragma no es necesario colocar calzos.

 Quando si sostituisce una frizione a molle elicoidali a 4 leve con una frizione di tipo a diaframma LuK, non sono necessari distanziatori.



133 0018 10



133 0608 10



133 0017 10



133 0271 10

- For accurate model information please see LuK catalogue
- Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog
- Pour plus d'information sur les applications veuillez vous référer au catalogue LuK
- Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK
- Per informazioni sul modello consultare il catalogo LuK

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER
REPXPPERT