POMP DIR LANDCRUISER 90

Remanufactured

Core code : 73

FCDADP

3599771000830



TECHNICAL DATA

Operating Mode	**hydraulic**
for steering manufacturer	**TOYODA**
Rotation Direction	**Clockwise rotation**
Overall Length [mm]	**96 mm**
Pressure Line Connection Thread Size	**Ø16mm**
Backflow Connector Thread Size	**F16x150**
Position of the input pipe [clock]	**4 hours (clock hand)**
Pulley fitting	**Toothed pinion**

PICTURES









Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

TOYOTA		
HILUX (97-05) Pick-up - 2.5 D-4D	88 ch	11.2001 > 07.2005
HILUX (97-05) Pick-up - 2.5 D-4D 4WD	102 ch	11.2001 > 07.2005
LAND CRUISER 90 (95-02) (J9_) - 3.0 TD	125 ch	04.1996 > 12.2002
LAND CRUISER 90 (95-02) (J9_) - 3.0 D-4D 4WD	163 ch	**10.2000 > 08.2002**
LAND CRUISER 70 (1984-) (J7_) - 3.0 TD	125 ch	05.1993 > 05.1996
LAND CRUISER 70 (90-96) Hardtop (J7_) - 3.0 TD	125 ch	05.1993 > 05.1996
HIACE IV Fourgon (__H1_, __H2_) - 2.5 D-4D	88 ch	08.2001 > 08.2006
HIACE IV Fourgon (__H1_, __H2_) - 2.5 D-4D 4WD	88 ch	08.2001 > 08.2004
HIACE IV Fourgon (__H1_, __H2_) - 2.5 D-4D	102 ch	08.2001 > 08.2006
HIACE IV Fourgon (__H1_, __H2_) - 2.5 D-4D 4WD	102 ch	08.2001 > 08.2006
HIACE IV Autobus/Autocar (__H1_, __H2_) - 2.5 D-4D	88 ch	08.2001 > 08.2006
	102 ch	08.2001 > 08.2006
HIACE IV Autobus/Autocar (__H1_, __H2_) - 2.5 D-4D 4WD	102 ch	11.2001 > 08.2006