POCH.JOINTS TURBO KIA

New part

FAVAAV

3599774267971

TECHNICAL DATA

Charge Type	**Exhaust Turbocharger**
Supplementary Article/Info 2	**with exhaust manifold gasket(s)**
Alternative Repair Kit	**WG2158489**

Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

HYUNDAI		
i40 (2011-) CW Break (VF) - 1.7 CRDi	116 ch	07.2011 > 05.2019
	136 ch	**02.2015 > 05.2019**
	141 ch	01.2015 > 05.2019
i40 (2012-) (VF) - 1.7 CRDi	116 ch	03.2012 > 05.2019
i40 (2012-) (VF) - 1.7 CRDI	141 ch	01.2015 > 05.2019
TUCSON (TLE) - 1.7 CRDi	116 ch	06.2015 > 09.2020
	141 ch	06.2015 > 09.2020

KIA		
CARENS IV (RP) - 1.7 CRDi	116 ch	03.2013 > 08.2016
	136 ch	03.2013 > 08.2016
	141 ch	07.2015 > 08.2016
OPTIMA (JF) - 1.7 CRDi	135 ch	09.2016 > 04.2018
	141 ch	11.2015 > 04.2018
OPTIMA Sportswagon (JF) - 1.7 CRDi	141 ch	09.2016 > 04.2018
SPORTAGE (QL) (US) - 1.7 CRDi	116 ch	09.2015 > 09.2022
CARENS IV Van (A4) - CRDi	116 ch	04.2015 > 08.2016
	136 ch	04.2015 > 08.2016
SPORTAGE (QL) (US) - 1.7 CRDi	141 ch	11.2016 > 09.2022