POMP DIR MATIZ 0.8 AV CLI

Remanufactured

Core code : 70

FCDADP

3599771716410



TECHNICAL DATA


Operating Mode	**hydraulic**
Belt Pulley Ø [mm]	**103 mm**
Pulleys	**with V-ribbed belt pulley**
Pulleys	**without belt pulley**
Supplementary Article/Info 2	**with sensor**
for steering manufacturer	**YOUNG SHIN**
Number of grooves	**4**
Position of the input pipe [clock]	**3 hours (clock hand)**
Pulley fitting	**Screwed**
Number of rear fixation points	**2**

PICTURES











Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

DAEWOO		
MATIZ (KLYA) - 0.8	52 ch	09.1998 >
MATIZ (KLYA) - 1.0	64 ch	01.2003 >