ALTERNATEUR BUICK,CADILLA

Remanufactured

Core code : 04

FADAAL

3599771203682



TECHNICAL DATA

Alternator Charging Current [A]	**80 A**
Fiche	**PLUG645**
Pulleys	**without belt pulley**
Info complémentaire	**with integrated regulator**
Clamp	**M6 B+**
Voltage [V]	**12 V**

PICTURES









Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

CHEVROLET		
CAMARO 81 (FP_) - 5.0	152 ch	12.1981 > 12.1992
MALIBU (80-83) 69 - 5.0	150 ch	01.1980 > 12.1983

JEEP		
WRANGLER (87-95) (YJ, SJ_) - 4.2	114 ch	08.1986 > 08.1989