ALTERNATEUR LEGACY

Remanufactured

Core code : 06

FADAAL

3599771210178



TECHNICAL DATA

Alternator Charging Current [A]	**70 A**
Fiche	**PLUG351**
Pulleys	**with V-ribbed belt pulley**
Info complémentaire	**with integrated regulator**
Number of grooves	**5**
Clamp	**M6 B+**
Voltage [V]	**12 V**

PICTURES









Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

SUBARU		
LEGACY (89-94) (BC) - 1800	103 ch	01.1989 > 12.1993
LEGACY (89-94) (BC) - 1800 4WD	103 ch	01.1989 > 09.1991
LEGACY (89-94) (BC) - 2000 4WD	116 ch	08.1991 > 07.1994
LEGACY (89-94) (BC) - 2000 Turbo 4WD	200 ch	05.1992 > 07.1994
LEGACY (89-94) (BC) - 2200 4WD	136 ch	01.1989 > 07.1994
LEGACY (89-94) Station Wagon (BJF) - 1800	103 ch	01.1989 > 07.1994
LEGACY (89-94) Station Wagon (BJF) - 1800 4WD	103 ch	01.1989 > 07.1994
LEGACY (89-94) Station Wagon (BJF) - 2000	116 ch	09.1991 > 12.1993
LEGACY (89-94) Station Wagon (BJF) - 2000 4WD	116 ch	09.1991 > 07.1994
LEGACY (89-94) Station Wagon (BJF) - 2000 Turbo Super 4WD	200 ch	05.1992 > 07.1994
LEGACY (89-94) Station Wagon (BJF) - 2200 Super 4WD	136 ch	01.1989 > 07.1994
LEGACY (94-99) (BD, BG) - 2.0 i	116 ch	09.1994 > 03.1999
LEGACY (94-99) (BD, BG) - 2.0 i 4WD	116 ch	09.1994 > 03.1999
LEGACY (94-99) (BD, BG) - 2.2 i 4WD	128 ch	09.1994 > 03.1999
LEGACY (94-99) Station Wagon (BD, BG) - 2.0 i	116 ch	09.1994 > 11.1998
LEGACY (94-99) Station Wagon (BD, BG) - 2.0 i 4WD	116 ch	09.1994 > 11.1998
LEGACY (94-99) Station Wagon (BD, BG) - 2.2 i 4WD	128 ch	**02.1994 > 11.1998**