ALTERNATEUR MAZDA 323

Remanufactured

Core code : 06

FADAAL

3599771210680



TECHNICAL DATA

Alternator Charging Current [A]	**70 A**
Fiche	**PLUG661**
Pulleys	**with V-ribbed belt pulley**
Info complémentaire	**with integrated regulator**
Number of grooves	**4**
Clamp	**M8 B+**
Voltage [V]	**12 V**

PICTURES









Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

MAZDA		
323 (94-98) C (BA) - 1.3 16V	73 ch	08.1994 > 09.1998
323 (94-98) C (BA) - 1.5 16V	88 ch	08.1994 > 09.1998
323 (94-98) C (BA) - 1.8 16V	114 ch	08.1994 > 09.1998
323 (94-98) F (BA) - 1.5 16V	88 ch	07.1994 > 09.1998
323 (94-98) F (BA) - 1.8 16V	114 ch	08.1994 > 09.1998
323 (98-04) F (BJ) - 1.4	72 ch	01.2001 > 05.2004
323 (98-04) F (BJ) - 1.3 16V	73 ch	09.1998 > 01.2001
323 (98-04) F (BJ) - 1.5 16V	88 ch	09.1998 > 01.2001
323 (98-04) F (BJ) - 1.6	95 ch	01.2001 > 05.2004
	98 ch	01.2001 > 05.2004
323 (94-98) P (BA) - 1.3 16V	73 ch	10.1996 > 09.1998
323 (94-98) P (BA) - 1.5 16V	88 ch	10.1996 > 09.1998
323 (94-98) S (BA) - 1.3 16V	73 ch	08.1994 > 09.1998
323 (94-98) S (BA) - 1.5 16V	88 ch	08.1994 > 09.1998
323 (94-98) S (BA) - 1.8 16V	114 ch	08.1994 > 09.1998
323 (98-04) S (BJ) - 1.3	72 ch	01.2001 > 05.2004
323 (98-04) S (BJ) - 1.3 16V	73 ch	09.1998 > 01.2001
323 (98-04) S (BJ) - 1.5 16V	88 ch	09.1998 > 01.2001
323 (98-04) S (BJ) - 1.6	95 ch	10.2000 > 05.2004
	98 ch	01.2001 > 05.2004
DEMIO (DW) - 1.3 16V	63 ch	**08.1998 > 12.2002**
DEMIO (DW) - 1.3 i 16V	72 ch	08.1998 > 04.2000
DEMIO (DW) - 1.5 16V	75 ch	04.2000 > 07.2003
MX-3 (EC) - 1.6 i	107 ch	11.1993 > 09.1998
MX-5 (98-05) (NB) - 1.6 16V	110 ch	05.1998 > 10.2005
MX-5 (98-05) (NB) - 1.8	140 ch	01.1998 > 07.2002
MX-5 (98-05) (NB) - 1.8 16V	140 ch	05.1998 > 10.2005