POMP DIR SONATA 3 2.0I 93

Remanufactured

Core code : 70

FCDADP

3599771283981



TECHNICAL DATA

Operating Mode	**hydraulic**
Belt Pulley Ø [mm]	**112 mm**
Pulleys	**without belt pulley**
Supplementary Article/Info 2	**with sensor**
for steering manufacturer	**YOUNG SHIN**
Overall Length [mm]	**114 mm**
Backflow Connector Thread Size	**F16x150**
Position of the input pipe [clock]	**12 hours (clock hand)**
Pulley fitting	**Screwed**
Number of rear fixation points	**1**

PICTURES











Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

HYUNDAI		
LANTRA (90-95) (J-1) - 1.5 i.e.	86 ch	10.1990 > 11.1995
LANTRA (90-95) (J-1) - 1.6 i.e. 16V	106 ch	10.1990 > 11.1995
	114 ch	10.1990 > 11.1995
LANTRA (90-95) (J-1) - 1.8 i.e. 16V	127 ch	10.1990 > 11.1995
SONATA (95-98) (Y-3) - 1.8 GLS	86 ch	07.1996 > 05.1998
SONATA (95-98) (Y-3) - 1.8 i	98 ch	05.1993 > 06.1998
SONATA (95-98) (Y-3) - 2.0 i	95 ch	08.1996 > 06.1998
	105 ch	06.1994 > 08.1996
SONATA (95-98) (Y-3) - 2.0 i 16V	125 ch	06.1996 > 06.1998
	139 ch	05.1993 > 06.1998
SONATA (95-98) (Y-3) - 3.0 i V6	146 ch	05.1993 > 06.1998