

DONNEES TECHNIQUES

Courant de charge [A]	65
Type de réseau de bord	pour véhicules 12V
Type de poulie	V
Pince	Plug B+
Connectique	PLUG110

PHOTOS




BULLETIN TECHNIQUE TB-02

Lors du montage de cet alternateur contrôlez bien qu'il n'y ait pas de fuites d'huile moteur ou fuites de gasoil (pompe d'injection).

Celles-ci provoqueraient des dégâts importants à l'alternateur. De par sa position prévue originellement sur le moteur, cet alternateur est très exposé à la saleté, l'eau, la poussière mais surtout à l'huile de moteur et au gasoil.


During mounting this alternator, please take care the vehicle doesn't show a leak of oil at the motor !!! This leak of oil causes severe damage to the alternator.

This alternator is very liable to dust, dirt, moisture and especially penetrating motor oil and/or diesel fuel.



BULLETIN TECHNIQUE TB-35

ATTENTION
Veuillez vérifier la poulie avec celle de la carcasse




Bornes	
B+	Positive
D+	Trio (Lamp)

DOCUMENTS

BT-130 Refus des carcasses alternateurs/démarrateurs

APPLICATIONS

ALFA ROMEO		
33 (905) - 1.3 (905.A1A/C/D/F/H)	86 ch	10.1984 > 12.1989
33 (905) - 1.3 (905.A1B, 905.A1C, 905.A1G)	75 ch	06.1983 > 12.1989
33 (905) - 1.5	95 ch	05.1983 > 12.1993
33 (905) - 1.5 (905.A2)	102 ch	07.1986 > 12.1989
33 (905) - 1.5 4x4 (905.A2A)	95 ch	01.1984 > 12.1989
33 (905) - 1.7	118 ch	01.1986 > 12.1989
	129 ch	01.1986 > 12.1989
33 (905) - 1.7 i.e. (905.A3D)	105 ch	09.1988 > 12.1989
33 (905) - 1.7 QV (905.A3)	114 ch	03.1988 > 12.1989
33 Sportwagon (905A) - 1.4	90 ch	01.1984 > 12.1988
33 Sportwagon (905A) - 1.5	102 ch	12.1986 > 12.1989
33 Sportwagon (905A) - 1.7	118 ch	03.1988 > 12.1989
33 Sportwagon (905A) - 1.7 i.e.	105 ch	09.1988 > 12.1989
33 Sportwagon (905A) - 1.7 i.e. 4x4	105 ch	09.1988 > 12.1989
33 (907A) - 1.4 4x4	90 ch	07.1990 > 12.1992
33 (907A) - 1.4 i.e. (907.A3A, 907.A3B)	88 ch	06.1991 > 09.1994
	90 ch	06.1991 > 09.1994
33 (907A) - 1.5	105 ch	01.1990 > 04.1993
33 (907A) - 1.5 i.e	97 ch	01.1990 > 09.1994
33 (907A) - 1.5 i.e. (907A2A)	101 ch	07.1990 > 08.1991
33 (907A) - 1.7 16V (907.A1B)	137 ch	01.1990 > 03.1992
33 (907A) - 1.7 16V (907.A1C)	129 ch	01.1990 > 09.1994
	132 ch	01.1990 > 03.1992
33 (907A) - 1.7 16V 4x4 (907.A1G)	129 ch	01.1990 > 09.1994
	132 ch	01.1990 > 09.1994
33 (907A) - 1.7 16V 4x4 (907A1F)	137 ch	01.1990 > 09.1994
33 (907A) - 1.7 i.e. (907.A1A)	105 ch	04.1992 > 09.1994
	107 ch	01.1990 > 03.1992
33 (907A) - 1.7 i.e. 4x4	107 ch	01.1990 > 03.1992
33 Sportwagon (907B) - 1.4 i.e.	90 ch	06.1991 > 09.1994
33 Sportwagon (907B) - 1.4 i.e. 4x4	90 ch	06.1991 > 09.1994
33 Sportwagon (907B) - 1.5 i.e	97 ch	01.1990 > 09.1994
33 Sportwagon (907B) - 1.7 16V	137 ch	01.1990 > 03.1992
33 Sportwagon (907B) - 1.7 16V (907.B1G)	129 ch	01.1990 > 09.1994
	132 ch	01.1990 > 09.1994
33 Sportwagon (907B) - 1.7 16V 4x4 (907.B1H)	129 ch	01.1990 > 09.1994
	132 ch	01.1990 > 03.1992
33 Sportwagon (907B) - 1.7 i.e. (907.B1A)	105 ch	04.1992 > 09.1994
	107 ch	01.1990 > 03.1992
33 Sportwagon (907B) - 1.7 i.e. 4x4 (907.B1E)	107 ch	01.1990 > 03.1992

 Avant montage, comparez la pièce reçue à celle d'origine afin de vérifier que la bonne pièce a été choisie et peut être montée sur le véhicule. Le non-respect de cette consigne ou des instructions de montage annule la garantie.