

## DONNEES TECHNIQUES

Type de réseau de bord	<b>pour véhicules 12V</b>
Puissance nominale [kW]	<b>1.2</b>
Nombre de dents	<b>8T</b>
Direction de rotation	<b>rotation CW</b>
Réducteur	<b>Avec réducteur (G/R) intégré</b>
Nombre de taraudages	<b>2</b>
Nombre de trous de fixation	<b>2</b>
Connectique	<b>SOL60</b>


## PHOTOS



### BULLETIN TECHNIQUE TB-05

Ce démarreur n'utilise pas de bobinage en cuivre ou en aluminium, mais utilise des aimants ferreux permanents. Si vous traitez ce démarreur brutalement (chute ou coup de marteau sur le démarreur ou le solénoïde), les aimants se fissureront ou casseront. Ceci entraînant la destruction du démarreur.

This starter doesn't use field coils made from copper or aluminium, but uses ferrite permanent magnets. If you treat this starter roughly (e.g. drop or hit on the starter motor or solenoid with a hammer) the magnets will crack or break. Causing the starter to fail.




## DOCUMENTS

**BT-130 Refus des carcasses alternateurs/démarrateurs**

## APPLICATIONS

<b>HYUNDAI</b>		
GALLOPER (91-98) - 3.0 V6	141 ch	08.1991 > 07.1998
SONATA (88-94) (Y-2) - 3.0 i V6	145 ch	01.1991 > 10.1993
<b>MITSUBISHI</b>		
3000 GT (Z16A) - 3.0 i 24V 4x4	286 ch	06.1992 > 08.1999
GALANT (93-96) (E5_A, E7_A, E8_A) - 2.5	170 ch	11.1992 > 09.1996
GALANT (93-96) (E5_A, E7_A, E8_A) - 2.5 V6-24 4x4 (E88A)	170 ch	11.1992 > 08.1996
GALANT (93-96) 3 volumes (E5_A, E7_A, E8_A) - 2.5 V6-24 4x4 (E88A)	170 ch	11.1992 > 08.1996
PAJERO (82-91) (L04_G, L14_G) - 3.0 V6 (L141G, L146G)	141 ch	11.1988 > 11.1990
PAJERO (91-99) (V2_W, V4_W) - 3.0 V6 (V23W, V43W, V23C)	150 ch	12.1990 > 12.1995
PAJERO (91-99) (V2_W, V4_W) - 3.0 V6 24V	177 ch	06.1997 > 04.2000
	181 ch	06.1994 > 05.1997
PAJERO (91-99) (V2_W, V4_W) - 3.5 V6 24V	194 ch	07.1997 > 04.2000
PAJERO (91-99) (V2_W, V4_W) - 3.5 V6 24V (V25W, V45W)	208 ch	06.1994 > 04.2000
PAJERO (91-99) Canvas Top (V2_W, V4_W) - 3.0 V6 (V23W, v43W, V23C)	150 ch	12.1990 > 12.1995
PAJERO (91-99) Canvas Top (V2_W, V4_W) - 3.0 V6 24V	181 ch	06.1994 > 04.2000
PAJERO (00-06) (V60, V70) - 3.5 V6 GDI (V65W, V75W)	203 ch	04.2000 >
PAJERO SPORT (96-08) (K90) - 3.0 V6	170 ch	06.2000 >
	177 ch	11.1998 >
SIGMA (F16A) - 3.0 V6 (F16A)	177 ch	12.1990 > 07.1996
	205 ch	12.1990 > 07.1996
SIGMA Break (F07W) - 3.0 (V6)	170 ch	01.1993 > 07.1996

 Avant montage, comparez la pièce reçue à celle d'origine afin de vérifier que la bonne pièce a été choisie et peut être montée sur le véhicule. Le non-respect de cette consigne ou des instructions de montage annule la garantie.