

## Camshaft Tightening Procedure Procedimiento de Apriete de Árboles de Levas

93050400	MAKE MARCA	ENGINE MOTOR	CAMSHAFT PINION TIGHTENING APRIETE PIÑÓN ÁRBOL LEVAS	CAMSHAFT BEARING TIGHTENING APRIETE COJINETE DEL ÁRBOL
Kilos	TOYOTA TOYOTA	4Y-EC 2Y (DYNA/HI-LUX) 4Y	9 Kpm	2.5 Kpm
Libras	TOYOTA TOYOTA	4Y-EC 2Y (DYNA/HI-LUX) 4Y	65 lbft	18 lbft

AJUSA IS NOT RESPONSIBLE FOR ANY UPGRADE AFTER THIS DOCUMENT HAD BEEN PRINTED. FOR MORE INFO, PLEASE VISIT OUR WEBSITE [www.ajusa.es](http://www.ajusa.es)

AJUSA NO SE RESPONSABILIZA DE CUALQUIER ACTUALIZACIÓN POSTERIOR A LA IMPRESIÓN DE ESTE DOCUMENTO. PARA MAYOR INFORMACIÓN VISITE NUESTRA PAGINA WEB [www.ajusa.es](http://www.ajusa.es)