

PRODUCT IDENTIFICATION

Austin Maestro Montego



FI033EU





There are 2 replacement possibilities, depending on the original assemblies. Check the original equipment spring seat height to determine the correct Monroe® replacement.

SENSA-TRAC	ORIGINAL	H
S1044 (N/A)	-	179 mm
S1045 (N/A)	R3311	160 mm

(N/A): Discontinued

Note (on Montego Estate) :

If the vehicle is fitted with a levelling system, the shock absorbers are provided with weaker springs. To fit the Monroe® shock absorbers the springs must be replaced in order to maintain the correct ride height (see Technical bulletins nr. 33 et 34)



REFLEX SENSATRAC	ORIGINAL	ORIGINAL
S1044 (N/A)	R3310 (N/A)	R3720
S1045 (N/A)	R3311	R3715

(N/A): Discontinued

Tightening torques (daNm)	
A	B
3	2.5
3	2.5