

PRODUCT IDENTIFICATION VISUAL DETAILS

Rover 800




FI057EU



5.88 > 92




92 > ...



67 mm



These shock absorbers do not possess the same operating characteristics



71 mm

TIGHTENING TORQUES			daN.m
2.5	A	Top mount nuts	2.5
6	B	Top stem nut	3.5
5	C	Lower mounting	6.5