




87 > ...

10.90 > ...

16537	ORIGINAL®	16574
-------	------------------	-------



These shock absorbers do not possess the same operating characteristics

TIGHTENING TORQUES		daN.m
A	Top mount bolts	1.4
B	Top stem nut	3.6
C	Lower mounting	4.5