

Main differences between kits MCK0392 and MCK1070

Chain kits **MCK0390**, **MCK0392** and **MCK1070** are dedicated to replacing the distribution system of some vehicles produced by HYUNDAI and KIA.

In particular, kit MCK1070 completes the coverage of vehicles not originally covered from MCK0390 and MCK0392; these are vehicles produced from 2008 on with Diesel engines from 1.100 to 1.700 cc CRDI.

It has to be noticed that some modifications have been introduced on two components: **upper slider 1** and **injection pump gear 2**.

Here below: pictures of modified components with indication of OE codes.

MCK0392

243352A000 2

Injection pump gear



1 **243872A010**

Upper slider

In this kit, the gear that controls the injection pump shows a plain front side. The rear side, instead, shows a small step. The bore is smooth.

The injection pump shaft pairs with the gear. A nut blocks both components.

FRONT VIEW



REAR VIEW



MCK1070

243352A210 2

Injection pump gear



1 **243872A300**

Upper slider

In this kit, the gear that controls the injection pump shows a front side with a little step; the rear side shows a raised edge. The bore is grooved.

The injection pump shaft shows a spline/tab that matches with the gear groove, improving the drag.

The injection pump shaft pairs with the gear. A nut blocks both components.

FRONT VIEW



REAR VIEW

