



LuK Service Info



Part Nr: 133 0270 10 / 133 0272 10 — 330MM TBFR

Manufacturer: NEW HOLLAND FORD

Info: 133 0272 10 replaces/ersetzt/
remplace/sustituye a/sostituisce
133 0004 50 & 133 0005 50


Model: 5000, 6000, 7000, 8000 & 9000 SERIES


Art.-Nr.: 133 0270 10


133 0270 10 replaces/ersetzt/
remplace/sustituye a/sostituisce
133 0020 11 & 133 0032 50 & 133 0245 10





633 3098 10 = 133 0270 10 + 332 0013 10 + 500 0199 40 + 410 0021 00
633 3207 00 = 133 0270 10 + 333 0032 10 + 500 0199 40 + 410 0021 00
633 3208 00 = 133 0270 10 + 333 0087 10 + 500 0199 40 + 410 0021 00
633 1126 19 = 133 0272 10 + 333 0032 10
633 1130 17 = 133 0272 10 + 333 0032 10 + 500 0199 40 + 410 0021 00
633 1127 09 = 133 0272 10 + 333 0033 06
633 1131 07 = 133 0272 10 + 333 0033 06 + 500 0199 40 + 410 0021 00
633 3074 09 = 133 0272 10 + 332 0013 10
633 3075 10 = 133 0272 10 + 333 0087 10 + 500 0199 40 + 410 0021 00
633 3075 09 = 133 0272 10 + 333 0087 10
633 3135 10 = 133 0272 10 + 332 0013 10 + 500 0199 40 + 410 0021 00

 When replacing a 4 lever coil spring clutch with LuK diaphragm type clutch, shims are not required.

 Al reemplazar el embrague de muelles helicoidales con 4 patillas por el de diafragma no es necesario colocar calzos.

 Wenn die 4-Hebel-Schraubenfederkupplung durch eine LuK-Tellerfederkupplung ersetzt wird, entfallen die Segmentbleche.

 Quando si sostituisce una frizione a molle elicoidali a 4 leve con una frizione di tipo a diaframma LuK, non sono necessari distanziatori.

 Le remplacement d'un embrayage à ressorts hélicoïdaux à 4 leviers par un embrayage à diaphragme LuK ne requiert pas de cales de réglage.



133 0020 11



133 0032 50



133 0004 50



133 0245 10



133 0005 50



133 0270 10



133 0272 10



- For accurate model information please see LuK catalogue
- Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog
- Pour plus d'information sur les applications veuillez vous référer au catalogue LuK
- Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK
- Per informazioni sul modello consultare il catalogo LuK

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER
REPXPPERT