



HYDRAULIC vs ROTARY TENSIONER

HYDRAULIC TENSIONER: T3034E



≠



T3034E: Hydraulic tensioner pulley for: MERCEDES Actros MP4/MP5 & Arocs

Hutchinson, O.E supplier for >15 years for this engine (previous version: T3034)

	Hydraulic	Rotary
Reliability of friction system	1 200 000 km	500 000 km
Performance (dissipated power)	High	Low

