



This is to certify that:



BM04010BA

Bumper Rear

Licence holder:Tong Yang Industry Co LtdManufacturer Code:49994CED0021Vehicle test fitted in:EuropeFits to:BMW 5 Series 1996 To 2000 4 Door Saloon

Part Image

Vehicle Image





Certified as having the following requirements successfully evaluated:

Vehicle Fit Tested, Production Surveyed

This certificate is only applicable for parts which have the Thatcham TUV Certified Part label attached

Date Issued

13th January 2010 Expiry Date January 2016



Peter Shaw Chief Executive Thatcham Research Certificate No:

TTC0296

Ofth

Ralf Schunk TÜVRheinland Italia S.r.l

Experts in Safety, Security and Crash Repair

THE MOTOR INSURANCE REPAIR RESEARCH CENTRE