


DEM. NEUF VISA-205-SAMBA
 New part

FANADN

 3599773316267


TECHNICAL DATA

Voltage [V]	12 V
Rated Power [kW]	0.7 kW
Number of mounting bores	3
Number of Teeth	9
Fiche	SOL65
Rotation Direction	Clockwise rotation
Number of threaded holes	3

PICTURES



Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

CITROËN

BX (XB_) - 14 E	61 ch	10.1982 > 06.1988
	71 ch	04.1983 > 07.1989
	72 ch	04.1983 > 02.1993
	80 ch	10.1985 > 05.1989
BX Break (XB_) - 1.4	60 ch	01.1987 > 01.1992
BX Break (XB_) - 14	72 ch	01.1986 > 02.1993
BX Break (XB_) - 1.4	71 ch	01.1987 > 01.1992
C15 Break - 1.4	60 ch	05.1987 > 10.1992
	67 ch	05.1987 > 09.1992
LNA - 1.0	45 ch	07.1984 > 10.1986
LNA - 1.1	50 ch	07.1982 > 04.1985
VISA - 1.0	45 ch	09.1984 > 06.1988
VISA - 11 E	48 ch	09.1978 > 06.1988
	50 ch	07.1982 > 03.1991
	57 ch	09.1978 > 03.1991
VISA - II Super X	64 ch	07.1980 > 06.1982
VISA - 14	60 ch	07.1984 > 03.1991
VISA - 14 GT	75 ch	03.1982 > 03.1987
	79 ch	03.1982 > 03.1991
VISA Cabriolet - 11 RE	50 ch	03.1983 > 10.1988
C15 Camionnette/Monospace (VD_) - 1.0	45 ch	10.1984 > 12.1997
C15 Camionnette/Monospace (VD_) - 1.1	48 ch	10.1984 > 12.1996
C15 Camionnette/Monospace (VD_) - 1.4 E	55 ch	07.1987 > 12.1996
	60 ch	05.1987 > 12.1996

HONDA

JAZZ - 1.3 HYBRID	102 ch	04.2011 >
-------------------	--------	-----------

PEUGEOT

104 - 0.9	46 ch	10.1972 > 10.1979
	45 ch	10.1979 > 10.1983
104 - 1.0	44 ch	09.1983 > 06.1988
104 - 1.1	50 ch	08.1980 > 06.1988
	57 ch	07.1976 > 08.1982
	66 ch	09.1978 > 09.1979
104 - 1.2	57 ch	08.1979 > 06.1983
104 - 1.4	72 ch	08.1979 > 06.1983
104 Coupe - 0.9	45 ch	09.1973 > 10.1983
104 Coupe - 1.1	67 ch	08.1975 > 06.1980
	50 ch	08.1979 > 06.1988
	57 ch	08.1979 > 06.1983
	66 ch	09.1973 > 09.1979
104 Coupe - 1.4	72 ch	08.1979 > 06.1984
205 (83-87) (741A/C) - 1.0	45 ch	02.1983 > 10.1987
205 (83-87) (741A/C) - 1.1	49 ch	02.1983 > 10.1987
	50 ch	02.1983 > 10.1987
205 (83-87) (741A/C) - 1.4	60 ch	02.1983 > 10.1987
	72 ch	02.1983 > 10.1987
	79 ch	10.1985 > 10.1987
	80 ch	02.1983 > 10.1987

PEUGEOT

205 (86-94) Cabriolet (741B, 20D) - 1.4 CJ	60 ch	03.1988 > 05.1989
205 (86-94) Cabriolet (741B, 20D) - 1.4 CT	79 ch	04.1986 > 12.1988
205 (87-98) (20A/C) - 1.0	45 ch	10.1987 > 09.1998
	50 ch	08.1992 > 05.1997
205 (87-98) (20A/C) - 1.1	49 ch	10.1987 > 10.1990
205 (87-98) (20A/C) - 1.4	60 ch	10.1987 > 05.1989
	72 ch	01.1987 > 07.1988
	79 ch	07.1988 > 05.1989
205 Camionnette/Berline bicorps trois ou cinq port - 1.1	49 ch	02.1983 > 07.1987
205 Camionnette/Berline bicorps trois ou cinq port - 1.4	60 ch	02.1983 > 07.1987
J7 Fourgon - 1.5	83 ch	08.1968 > 07.1970

RENAULT

14 (121_) - 1.2	57 ch	05.1976 > 01.1980
	58 ch	01.1980 > 12.1983
14 (121_) - 1.4	60 ch	12.1981 > 12.1983
	71 ch	09.1979 > 06.1983

SSANGYONG

TIVOLI - 1.6 XDi 160	115 ch	04.2015 >
TIVOLI - 1.6 XDi 160 Traction intégrale	115 ch	04.2015 >
XLV SUV - e-XDi 160	116 ch	04.2016 >
XLV SUV - e-XDi 160 Traction intégrale	116 ch	04.2016 >

TALBOT

SAMBA (51A) - 0.9	42 ch	01.1981 > 12.1985
SAMBA (51A) - 1.1	50 ch	01.1981 > 06.1986
SAMBA (51A) - 1.2 Rallye	88 ch	01.1983 > 10.1986
SAMBA (51A) - 1.4	60 ch	06.1983 > 10.1986
	72 ch	01.1981 > 06.1986
SAMBA (51A) - 1.4 Rallye	79 ch	01.1983 > 10.1986
SAMBA Cabriolet (51E) - 1.4	79 ch	01.1981 > 06.1986