


COMPRESSEUR DAEWOO MATIZ


Remanufactured

Core code : 85

FCCACC



3599771035955


TECHNICAL DATA

Manufacturer Restriction	Harrison
Voltage [V]	12 V
Belt Pulley Ø [mm]	105 mm
Pulleys	with V-ribbed belt pulley
Supplementary Article/Info 2	with magnetic clutch
Oil Fill Quantity [ml]	135 ml
Compressor Oil	PAG 46
Compressor ID	SP10
Clutch ID	PVR4
Number of grooves	4
Refrigerant	R 134a

PICTURES


Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

CHEVROLET		
MATIZ - 0.8	52 ch	03.2005 > 12.2013
MATIZ - 0.8 LPG	52 ch	03.2005 > 12.2007
MATIZ - 1.0	64 ch	03.2005 > 12.2007
	65 ch	01.2007 >
	67 ch	03.2005 >
MATIZ - 1.0 LPG	67 ch	03.2005 > 03.2011
SPARK - 0.8	50 ch	05.2005 > 02.2010
SPARK - 1.0 SX	63 ch	05.2005 >
	67 ch	05.2005 >

DAEWOO		
MATIZ (KLYA) - 0.8	52 ch	09.1998 >
MATIZ (KLYA) - 1.0	64 ch	01.2003 >
MATIZ (M200, M250) - 0.8	52 ch	01.2005 > 06.2010
MATIZ (M200, M250) - 1.0	67 ch	03.2005 > 12.2008