



ALTERNATEUR BRONCO



Remanufactured

Core code : 03

FADAAL




3599771203620



TECHNICAL DATA

Alternator Charging Current [A]	130 A
Fiche	PLUG656
Pulleys	with V-ribbed belt pulley
Info complémentaire	with integrated regulator
Connector/Clamp	with connection for speed sensor
Number of grooves	6
Clamp	M6 B+
Voltage [V]	12 V

PICTURES



Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

FORD USA

EXPLORER (U2) - 4.0 V6 4WD	165 ch	01.1993 > 12.1994
	156 ch	03.1995 > 12.2001