

Differenze tra il semiasse sinistro 17-0926/655-926 e destro 17-0927/655-927

Differences between driveshaft left 17-0926/655-926 and right 17-0927/655-927

Fiat Croma (194) : 1.9 MJT 16v

Il semiasse destro 17-0927/ 655-927 differisce dal semiasse sinistro 17-0926/655-926 per:

The main differences between the right driveshaft 17-0927/ 655-927 compared to the left driveshaft 17-0926/655-926 are:

- lavorazioni diverse dell'asta lato cambio / different machining of the gear box side rod
- presenza del cuscinetto sull'asta del lato cambio / bearing on the gear box side shaft included
- presenza della staffa di fissaggio / flange on the gear box side shaft included

17-0926/655-926



17-0927/655-927

