

Camshaft Tightening Procedure Procedimiento de Apriete de Árboles de Levas

93162100	MAKE MARCA	ENGINE MOTOR	CAMSHAFT PINION TIGHTENING APRIETE PIÑÓN ÁRBOL LEVAS	CAMSHAFT BEARING TIGHTENING APRIETE COJINETE DEL ÁRBOL
Kilos	AUDI, SEAT SKODA AUDI, SEAT SKODA	AFK,AHW,AKQ,APE	2 kpm + 90°	2 Kpm
Libras	AUDI, SEAT SKODA AUDI, SEAT SKODA	AFK,AHW,AKQ,APE	14 lbft + 90°	14 lbft

AJUSA IS NOT RESPONSIBLE FOR ANY UPGRADE AFTER THIS DOCUMENT HAD BEEN PRINTED. FOR MORE INFO, PLEASE VISIT OUR WEBSITE www.ajusa.es

AJUSA NO SE RESPONSABILIZA DE CUALQUIER ACTUALIZACIÓN POSTERIOR A LA IMPRESIÓN DE ESTE DOCUMENTO. PARA MAYOR INFORMACIÓN VISITE NUESTRA PAGINA WEB www.ajusa.es