

SKF Product Information

VKBA 3540 – Mandatory replacement of the washer included in the wheel bearing kit



Fiat Group, PSA, Ford, Abarth



Mandatory replacement of the washer during the wheel bearing fitting



	Fiat Group	PSA	Ford	Abarth
OE Nb's	71769737, 71769738	16 066 355 80	1 587 590	51754193

To ensure a complete and professional repair, the washer provided in the wheel bearing kit (from batch code 174S) must be changed during the mounting.

Note! When installing the new Wheel Bearing:

- ✓ Always follow the mounting instruction MI-537930 to remove the old wheel bearing
- ✓ Remove the old washer
- ✓ Use the new included Washer
- ✓ Continue to install the new wheel bearing

VKBA 3540



YouTube [Click here to watch SKF technical videos on Youtube!](#)

© SKF Group 2020

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use

