

INFORMATION PRODUIT SKF

VKBA 3540 – Changement obligatoire de la rondelle incluse dans le kit de roulement de roue.



Groupe FIAT, PSA, Ford, Abarth



Changement obligatoire de la rondelle lors du montage du roulement de roue




	Groupe FIAT	PSA	Ford	Abarth
N° OE	71769737, 71769738	16 066 355 80	1 587 590	51754193

Pour assurer une réparation complète et professionnelle, la rondelle qui est fournie dans le kit de roulement de roue (à partir du lot 174S) doit être changée pendant le montage.

Remarque ! Lors de l'installation du nouveau roulement de roue :

- ✓ Toujours suivre les instructions de montages MI-537930 pour retirer l'ancien roulement
- ✓ Retirer l'ancienne rondelle
- ✓ Utiliser la nouvelle rondelle qui est incluse
- ✓ Continuer à installer le nouveau roulement

VKBA 3540



YouTube [Cliquez ici pour regarder les vidéos techniques de SKF sur YouTube!](#)



© SKF Group 2020

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use

