



PI 1861
For technical personnel only!
1/1

PRODUCT INFORMATION

MERCEDES-BENZ CWA 400 ELECTRICAL WATER PUMP

DURING REPLACEMENT: SEPARATE INLET CONNECTION PIECES REQUIRED

With the vehicles listed below, an electrical water pump with OEM reference number A 274 200 01 07 was installed at the start of serial production. These water pumps were replaced by the water pump with the reference number A 274 200 02 07 during series production (from 09/2015), including a modified inlet connection piece on the intake side.

PLEASE NOTE WHEN ORDERING:

If the original installed water pump A 274 200 01 07 is replaced with the new version A 274 200 02 07 (corresponds to 7.05171.65.0), the inlet connection piece¹⁾ A 274 200 02 56 available separately must also be used.

¹⁾ This inlet connection piece is currently not yet available at Motorservice.



Ref. no.*	Pierburg no.	Replacement for	Engine	Vehicles
A 274 200 01 07	7.05171.65.0 + A 274 200 02 56 ¹⁾	7.05171.10.0	M 274.910 B	SLK (R172), GLK-CLASS (X204), GLC (X253), SLK (R172), C-CLASS (W204, W205), E-CLASS (W212) up to date 01.09.2015
		7.05171.15.0	M 274.920 BG	
		7.05171.16.0	up to engine number 30511340	
		7.05171.17.0		
A 274 200 02 07	7.05171.65.0	7.05171.25.0	M 274.910 B M 274.920 BG from engine number 30511341	SLK (R172), GLK-CLASS (X204), GLC (X253), SLK (R172), C-CLASS (W204, W205), E-CLASS (W212) from date 01.09.2015

All content including pictures and diagrams is subject to change. For assignment and replacement, refer to the current catalogues or systems based on TecAlliance.

* The reference numbers given are for comparison purposes only and must not be used on invoices to the consumer.