DEMARREUR GRANADA 1.8,2.0

Remanufactured

Core code : 03

FADADE

3599771305379



TECHNICAL DATA

Voltage [V]	**12 V**
Rated Power [kW]	**0.8 kW**
Number of mounting bores	**3**
Number of Teeth	**10**
Fiche	**SOL70**
Rotation Direction	**Clockwise rotation**

PICTURES









Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

FORD		
CAPRI (74-77) (GECP) - 1.3	54 ch	02.1974 > 08.1977
CAPRI (78-87) (GECP) - 1.6	73 ch	01.1978 > 04.1987
CAPRI (78-87) (GECP) - 2.0	101 ch	01.1978 > 12.1985
	90 ch	01.1978 > 12.1982
SIERRA (87-93) (GBG, GB4) - 2.0 i	100 ch	01.1987 > 12.1989
SIERRA (87-93) (GBG, GB4) - 2.0 i Cat	100 ch	01.1987 > 02.1993
SIERRA (87-93) (GBG, GB4) - 2.0	105 ch	01.1987 > 02.1993
SIERRA (87-93) (GBG, GB4) - 2.0 i	115 ch	01.1987 > 02.1993
SIERRA (87-93) 3/5 portes (GBC, GBG) - 2.0 i	100 ch	01.1987 > 02.1993
SIERRA (87-93) 3/5 portes (GBC, GBG) - 2.0 i Cat	100 ch	01.1987 > 02.1993
SIERRA (87-93) 3/5 portes (GBC, GBG) - 2.0 i	115 ch	01.1987 > 02.1993
	120 ch	06.1989 > 02.1993
SIERRA (87-93) Break (BNG) - 2.0 i	100 ch	01.1987 > 02.1993
	120 ch	05.1989 > 02.1993
TRANSIT Camion plate-forme/Châssis (V_ _) - 1.6	65 ch	11.1977 > 10.1986