**DEMARREUR MITSUBISHI CELE**

Remanufactured

Core code : 04

FADADE

3599771308752




## TECHNICAL DATA


| | |
|---|---|
| Voltage [V] | **12 V** |
| Rated Power [kW] | **1.2 kW** |
| Number of mounting bores | **2** |
| Transmission Type | **with reduction gear** |
| Number of Teeth | **9** |
| Fiche | **SOL36** |
| Rotation Direction | **Clockwise rotation** |
| Number of threaded holes | **2** |

## PICTURES











Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

| HYUNDAI | | |
|---|---|---|
| PONY 3 volumes (X-3) - 1.3 | 60 ch | 10.1994 > 01.2000 |
| PONY 3 volumes (X-3) - 1.3 i 12V | 84 ch | 10.1994 > 01.2000 |
| PONY 3 volumes (X-3) - 1.5 i 12V | 88 ch | 10.1994 > 01.2000 |
| PONY 3 volumes (X-3) - 1.5 i 16V | 99 ch | 10.1995 > 01.2000 |
| PONY (X-3) - 1.5 i 12V | 88 ch | 10.1994 > 01.2000 |
| PONY (75-82) - 1.4 | 68 ch | 08.1977 > 12.1985 |
| PONY Wagon - 1.4 | 68 ch | 02.1978 > 06.1986 |
| PONY (X-1) - 1.3 | 68 ch | 10.1985 > 09.1989 |
| PONY (X-2) - 1.3 | 67 ch | 10.1989 > 01.1995 |
| PONY (X-2) - 1.5 i | 83 ch | 10.1989 > 01.1995 |
| | 84 ch | 10.1989 > 01.1995 |
| PONY/EXCEL 3 volumes (X-2) - 1.5 | 72 ch | 01.1990 > 01.1995 |
| PONY/EXCEL 3 volumes (X-2) - 1.5 i | 84 ch | 01.1990 > 01.1995 |
| S COUPE (SLC) - 1.5 i | 84 ch | 02.1990 > 05.1996 |

| MITSUBISHI | | |
|---|---|---|
| GALANT (76-80) (A12_) - 2.0 GLX | 86 ch | 01.1977 > 08.1980 |
| GALANT (76-80) Break (A12_V) - 2.0 GLX | 98 ch | 01.1979 > 08.1980 |
| GALANT (80-84) (A16_) - 2.0 GLS | 102 ch | 09.1980 > 05.1984 |
| GALANT (80-84) (A16_) - 2.0 Turbo ECi | 170 ch | 05.1982 > 05.1984 |
| GALANT (80-84) Break (A16_V) - 2.0 GLX | 102 ch | 09.1980 > 06.1983 |
| GALANT (84-87) (E1_A) - 2.0 GLS | 102 ch | 06.1984 > 04.1990 |
| GALANT (84-87) (E1_A) - 2.0 Turbo ECi | 150 ch | **06.1984 > 05.1985** |
| GALANT (84-87) (E1_A) - 2.4 GLS | 112 ch | 07.1985 > 04.1990 |
| LANCER (79-83) (A17_) - 1.6 | 82 ch | 09.1979 > 02.1983 |
| | 84 ch | 01.1981 > 02.1983 |
| LANCER (79-83) (A17_) - 2.0 Turbo ECi | 170 ch | 03.1981 > 02.1983 |
| CELESTE (A7_) - 2.0 GSR | 90 ch | 10.1975 > 06.1981 |
| | 97 ch | 01.1977 > 06.1981 |
| | 105 ch | 01.1979 > 06.1981 |
| PAJERO (82-91) Canvas Top (L04_G) - 2.6 | 103 ch | 01.1983 > 11.1990 |
| PAJERO (82-91) (L04_G, L14_G) - 2.6 4WD | 107 ch | 10.1986 > 05.1991 |
| SPACE WAGON (D0_V/W) - 2.0 GLX | 84 ch | 06.1986 > 05.1988 |
| SPACE WAGON (D0_V/W) - 2.0 GLX 4WD | 84 ch | 06.1986 > 05.1988 |
| SPACE WAGON (D0_V/W) - 2.0 GLXi | 101 ch | 06.1988 > 04.1991 |
| SPACE WAGON (D0_V/W) - 2.0 GLXi 4WD | 101 ch | 06.1988 > 04.1991 |
| SPACE WAGON (D0_V/W) - 2.0 4WD | 102 ch | 03.1985 > 04.1991 |
| STARION (A18_A) - 2.0 Turbo ECi | 170 ch | 06.1982 > 12.1985 |
| | 180 ch | 05.1985 > 08.1987 |
| STARION (A18_A) - 2.6 Turbo ECi | 155 ch | 09.1987 > 06.1990 |
| L 300 / DELICA II Fourgon (L03_P) - 1.6 | 65 ch | 05.1980 > 10.1986 |