DEMARREUR SSANGYONG

Remanufactured

Core code : 11

FADADE

3599771060247



TECHNICAL DATA

Voltage [V]	**12 V**
Rated Power [kW]	**1.4 kW**
Number of mounting bores	**2**
Number of Teeth	**11**
Clamp	**M8 B+**
Clamp	**Pin "50" Plug**
Rotation Direction	**Clockwise rotation**
Flange Diameter [mm]	**77 mm**
Number of threaded holes	**1**

Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

SSANGYONG		
TIVOLI - 1.6	128 ch	04.2015 >
TIVOLI - 1.6 Traction intégrale	128 ch	03.2015 >
TIVOLI - 1.6 CNG	128 ch	07.2018 >
XLV SUV - 1.6 CNG	128 ch	07.2018 >
XLV SUV - e-XGi 160	128 ch	04.2016 >
XLV SUV - e-XGi 160 Traction intégrale	128 ch	04.2016 >