DEMARREUR SIERRA 1.8 TURB

Remanufactured

Core code : 06

FADADE

3599771314487



TECHNICAL DATA

Voltage [V]	**12 V**
Rated Power [kW]	**1.8 kW**
Number of mounting bores	**3**
Transmission Type	**with reduction gear**
Number of Teeth	**10**
Fiche	**SOL66**
Rotation Direction	**Clockwise rotation**
Technical Information Number	**BT-05**
Number of threaded holes	**3**

PICTURES









Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

FORD		
ESCORT (90-92) (GAL) - 1.8 TD	90 ch	02.1993 > 01.1995
ESCORT (90-92) Break (GAL, AVL) - 1.8 TD	90 ch	02.1993 > 01.1995
ESCORT (95-00) Cabriolet (ALL) - 1.8 TD	90 ch	09.1995 > 08.1998
ESCORT (92-95) 3 volumes (GAL) - 1.8 TD	90 ch	08.1993 > 01.1995
ESCORT (95-00) 3 volumes (GAL, AFL) - 1.8 TD	90 ch	01.1995 > 02.1999
ESCORT (95-00) (GAL, AAL, ABL) - 1.8 TD	90 ch	01.1995 > 10.1998
ESCORT (95-00) Clipper (GAL, ANL) - 1.8 TD	90 ch	01.1995 > 02.1999
ESCORT CLASSIC (AAL, ABL) - 1.8 TD	90 ch	10.1998 > 07.2000
ESCORT CLASSIC Turnier (ANL) - 1.8 TD	90 ch	02.1999 > 07.2000
P 100 II - 1.8 TD	75 ch	10.1987 > 12.1992
SIERRA (87-93) (GBG, GB4) - 1.8 TD	75 ch	08.1988 > 02.1993
SIERRA (87-93) 3/5 portes (GBC, GBG) - 1.8 TD	75 ch	08.1988 > 02.1993
SIERRA (87-93) Break (BNG) - 1.8 TD	75 ch	08.1988 > 02.1993
ESCORT VI Fourgon/Break (AVL) - 1.8 TD	90 ch	01.1995 > 08.2000