

KIA PICANTO CLUTCH CABLE INSTALLATION INFORMATION

CABLES



Issue Date: 03/04/18 Issue Number: CATB0008B

APPLICATION: Kia Picanto 1.0, 1.1 (2004 > 2007)

APPLICABLE REFERENCES: BKC1495

INSTALLING BKC1495

When installing the Clutch Cable on a Kia Picanto 2004 > 2007 it is essential that the connection to the bulkhead is installed correctly.

The cable has been manufactured to go through the bulkhead at a set angle so that when fitted to the clutch pedal a smooth in-line operation will be achieved.

If the connection is installed 180° out (upside down) this will result in the inner wire facing the opposite direction and therefore it will have to bend to fit the clutch pedal.

This will result in the inner wire cutting into the conduit culminating in the failure of the inner wire and the subsequent failure of the clutch cable.



FAILED CABLE DUE TO INCORRECT FITMENT OF BKC1495

If the flange is fitted in wrong way (rotation of 180°), the wire rope will have to bend to fit on the pedal. This will induce rapid wear and failure of the cable.

Please Note: evidence of the cable being installed incorrectly will invalidate the warranty.



Technical Information

If you require any further information please visit our website or contact the Technical Department on +44 (0)1869 329 709

www.borgandbeck.com



First Line Ltd, Chalker Way, Banbury, Oxon, OX16 4XD, UK